

# ATTACHMENT "D"

## Inspection Summary

Ticket number: 13-4726  
Inspection I.D.: M06  
Pipe Name: 440643  
Address: 4600 Elmont Dr  
Start: 432691  
End: 149872  
Direction: Upstream  
Size: 36"  
Material: RCP  
Footage Inspected: 609.9'

### Summary:

There was sediment build up in multiple spots in this inspection. There were multiple taps into this line from inlets on Elmont Dr. We had to end the inspection where inlet 183764 tap came in do to sediment build up.